

SEWING MACHINE TABLE
COMFORT 5 (C5L , C5XL)
COMFORT 5+ (C5L+ , C5XL+)



SYMBOLS



ATTENTION




ASSEMBLY & ADJUSTMENT



OPERATION




STORAGE




INDICATING MARK




SPECIAL OPERATION



WATCH




EQUALITY




EVEN SURFACE


010001	1x	010002	1x	010003	1x
010004	1x	010006	1x	010007	1x
010008	1x	010009	1x	010010	1x
010011	2x	010012	2x	010013	2x
010014	1x	010015	1x	010016	1x
010028	1x				

 020001 4x	 020002 2x	 020003 2x	 020004 2x 020005 2x	
 020006 2x	 020008 1x	 020010 2x L 660	 020011 1x	 020012 1x
 1 x 020007		 2x 020016		
 3x 020013 CR		 3x 020013 CL		
 3x 020015 DR		 3x 020015 DL		



030001  3 * 16 60x	030002  3,5 * 16 29x	030003  6,2 * 50 14x	030004  φ 5 * 16 6x	030005  4,2 * 16 10x	030006  2,9 * 13 6x	030007  φ 6 2x	030008  φ 4 4x	030009  M4 * 20 4x	030010  φ 6 4x
030011  φ 15 14x	030012  φ 18 9 x	030013  L 35 9 x	030014  φ 15 h 12 9 x	030015  φ 8 * 30 12x	030016  φ 8 * 30 4x	030017  φ 15 h10 4x	030033  4,2 * 13 18x		




COMFORT 5+ (C5L+, C5XL+)







010018 1x 010019 1x	020001  1x	5x 020019  5x	030004  φ 5 * 30 1x	030033  4,2 * 13 20x
------------------------	---	---	---	--





*
Included into table set.













2x 010012

2x 010013





2x 010011






030033







COMFORT 5+ (C5L+, C5XL+)




1x 050006







6



7

