



SEWING MACHINE TABLE

COMFORT EASY



SYMBOLS



ATTENTION




ASSEMBLY & ADJUSTMENT




OPERATION




STORAGE




INDICATING MARK



EQUALITY







EVEN SURFACE



STEP No

010009	1x	010013	1x	010018	1x	010022	1x
010023	1x	010024	1x	010025	1x	010027	1x
010029	1x	010030	1x				







14 030013
10x 

010023

030015 **15**
9x 

16 10x 030014 
10x 030012 

8x 030001 
4x 020024 
17

=
8x 030001 
4x 020056 
17

010029

6x 030005 
2x 020086 
18

010018

030005 
4x  **19**

20 **1x** 050006



