

SEWING MACHINE TABLE

COMFORT EASY plus



SYMBOLS



ATTENTION




ASSEMBLY & ADJUSTMENT



OPERATION




STORAGE




INDICATING MARK



EQUALITY



EVEN SURFACE





STEP No

010001 1x	010002 1x	010004 1x	010006 1x
010007 1x	010011 2x	010012 2x	010013 2x
010015 1x	010026 1x	010028 1x	010030 1x
010033 1x	010034 1x		

020003 2 x 	020006 2 x 	020011 2 x 	020012 2 x 	020018 4 x 
--	--	--	--	---


020019 3 x 	020020 4 x 	020056 4 x 	020084 2 x 
--	--	--	--

3 x 020013 CR 	3 x 020013 CL 
---	--

3 x 020015 DR 	3 x 020015 DL 
---	--

030001  3 * 16 20x	030002  3,5 * 16 36x	030003  6,2 * 50 14x		030033  4,2 * 13 22x	030006  2,9 * 13 4x
030008  φ4 4x	030009  M4 * 20 4x	030011  φ15 14x	030012  φ18 6x	030013  L = 35 6x	030014  φ15 h12 6x
030015  φ8 * 30 8x	030016  φ8 * 30 4x	030017  φ15 h10 4x	030028  3,9*16 8x		

1 x 050001 	1 x 050002 	1x 050004 
1x S4 	1 x 050003 	





010007

5

030008 030009
4x 4x
2x 020006

6

020011

2x



8x

030002

7

020003

2x



6x

030033

010015

010001

030015

10

4x



11

030013

6x



12

6x

030014



6x

030012



010007

010015

9

020012

030006

2x



4x

8

8x



030028


12x



030002





4x 020018



2x 010012

2x 010013

2x 010011



18


030002

4x

1x 050004



1x 010028





010002

19



2x 020084

20



12x



030033



3x 020019




030033



~4MM

1x 010034



23

4x 020020



21

030033
2x

1x 050001



22



1x 050003



1x 050002

2x

030033



