

SEWING MACHINE TABLE
COMFORT 6 (C6L , C6XL)

var 1



var 2




SYMBOLS



ATTENTION




ASSEMBLY & ADJUSTMENT




OPERATION




STORAGE




INDICATING MARK




SPECIAL OPERATION



WATCH





EQUALITY






EVEN SURFACE

010001	2x	010002	2x	010003	2x	010004	2x
010006	2x	010007	2x	010008	2x	010009	2x
010011	3x	010012	3x	010013	3x	010023	1x
010024	1x	010025	1x	010026	1x	010027	1x
010028	2x	010041	1x				

020001  4x	020002  4x	020003  2x	020004 2x  020005 2x 			
020006  6x	020008  2x	020010  2x L 660	020011  2x	020012  2x	020021  4x	
5x 020013 CR 			5x 020013 CL 			
5x 020015 DR 			5x 020015 DL 			

030001  3 * 16 68x	030002  3,5 * 16 36x	030003  6,2 * 50 28x	030038  2,5 * 20 8x	030005  4,2 * 16 20x	030006  2,9 * 13 8x	030007  φ6 4x	
030008  φ4 12x	030009  M4 * 20 12x	030010  φ6 8x	030011  φ15 26x	030012  φ18 16x	030013  L = 35 16x	030033  4,2 * 13 54x	
030014  φ15 h12 16x	030015  φ8 * 30 18x	030016  φ8 * 30 6x	030017  φ15 h10 6x	030061  M 8 4x	030060  φ8 4x	030027  M4 * 35 2x	030031  φ8 s2,5 4x





- 1** 8 x  030011
030003
8 x 

010003

010006


010008


010004


- 2** 020001
2 x 
030033
6 x 

- 3** 020002
2 x 
030033
6 x 

* Included into table set.








16

030005
4x




030010



17

S10



19




1 x 050003





2 x 050002

4 x 030033

030033



18

8 x 030033



4 x 050001




var 1

var 2



var 2


010023



21 4x 030011
4x 030003

010023

var 1



23 030013

4x

24


4x

030014

4x

030012

010024



010027

20

030002

10x



020013 CR

5x


22 6x

030011

6x

030003

010025



010026


25

4x 030061

4x 030031

4x 030060

4x 020021



* Included into table set.




30

6x 030001

3x 020015 DR

030016 **27**

6x



28

6x 030017

30

3x 020015 DL

6x 030001

29

030009 030008


6x 030001 6x 030008

3x 020006

26

030015

6x



32

030002

4x



1x 050004

33

030001

2x

1x 020015 DR



34

030003

2x

31

030027 030008

2x 030001 2x 030008






1x 020006

33

030001

2x

1x 020015 DL





R





R

=



L





6

